US ERA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Na			2. Date Prepared	3. Time Prepared	
		Kalamazoo River/Enbridge Oil Spill		06/02/2012	1600		
1. Unit Name/Designators		5. Unit Leader (Name and Position) 6. Operation				6. Operational Period	
Situa	tion Unit	Melinda Luetke, Planning Section Chief 0700, 05/31/12 –					
					0700, 06/07/12		
			Person	nel Ros	ter Assigned		
	Name		ICS Posi			Home Base	
	Matthew Haak	Situation Unit Leader			,	Chicago, Illinois	
3.	auo		Activity				
Time					inte		
	Major Events Overeflight Operational status						
09:00	Overflight Operational status:						
	Source area pond, sheen observed.						
	MP0.6 LDB Talmadge Creek, sheen observed.						
	Frac-Tank City, footprint reduction continues.						
	Frac-Tank City decon pad, no activity observed.						
	 MP1.1 Just west of I-69 Talmadge Creek LDB, sheen observed. 						
	· Pond east of confluence, sheen observed.						
	· Confluence, no sheen observed.						
	· Saylor's Landing, observed public fishing.						
	• MP5.0 RDB, sheen observed.						
	• MP5.25 RDB, sheen observed.						
	· Ceresco Dam, observed crew performing boom maintenance.						
	· Ceresco Dam, sheen observed.						
	MP7.5 Island, sheen observed. MP10.0 Reling grow observed.						
	 MP10.0, Poling crew observed. MP10.75RDB, sheen observed. 						
		• MP11.25, Poling crew observed.					
	• MP11.25R1, sheen observed.						
	• MP11.25R2, sheen observed.						
	• MP11.25, sheen observed.						
	• MP13.75, Poling crew observed.						
	• MP15.5 LDB, sheen observed.						
	• MP21.5, no sheen observed.						
	MP22.1 back water area, sheen observed.						
	MP24.0, Poling crew observed.						
	· MP26.0 Pond, sheen observed.						
	MP27.0 RDB, sheen observed.						
	· MP27.75, Poling crew observed.						
	· MP30	MP30.8, containment branch crew observed, sheen observed within boom.					
	MP19.25 Sediment Control Structure.						
	· Morrow Lake Delta, Poling Crew observed.						
	 Morrow Lake Delta, sheen observed within island vegetation. 						
	Sweep boat observed operating above E4 boom.						
	Observed velocity measurements being taken in Lake Morrow.						
	Morrow Lake sweep boat operating along the north shore line.						
	Morrow Lake Dam, observed two fishing boats below the dam.						
	Additional observations: None						
15:00	Return to ICP.						
). Prepare	ed by (Name an	d Position)				
3.7		**		T + D T			

Matthew Haak, Situation Unit Leader, USEPA-START